



AAA Garage Door, Inc.
803 S Platte Ave
Fremont, Nebraska 68025
(402) 727-0789

Estimate Id 73486909
Estimate Date 7/23/2026

Billing Address

McNeil Company
4666 South 132nd Street
Omaha, NE 68137 USA

Job Address

Crockett Residence
1702 South 150th Street
Omaha, NE 68144 USA

Estimate Details

18'x8' & 10'x8' (Gallery Alternate)

Furnish and install doors and openers

DESCRIPTION	QTY
Sommer 2060 evo+ up to 8' WITH TRANSMITTER	1
Sommer 2060 evo+ up to 8' WITH TRANSMITTER	1

DESCRIPTION	QTY
(1) Gallery® Steel - Premium Series Size : 18'0" x 8'0" Windcode : W0 Model : GD2LP Design : Long Panel Construction : 3-layer 2" Polystyrene Insulation R-value 9.0 Base Color : Bronze Top Section : Long Solid Glass Type : Not Applicable With Solid Top Section. Spring : Coated Torsion Track Size : 2" Flag & Jambs Separate Track Type : Standard Mount Type : Bracket Track Radius : 15 Handles : Standard Handles Included Hinges : Show No Hinge Step Plates : Show No Step Plate Lock : Inside Slide Lock Lock Options : No Lock Hole (Std with no lock and inside slide lock optional on #1 & #3) Other Items : Gold Bar Upgrade Shaft : Standard Shaft Vinyl Stop Mold : Bronze	1
(1) Gallery® Steel - Premium Series Size : 10'0" x 8'0" Windcode : W0 Model : GD2LP Design : Long Panel Construction : 3-layer 2" Polystyrene Insulation R-value 9.0 Base Color : Bronze Top Section : Long Solid Glass Type : Not Applicable With Solid Top Section. Spring : Coated Torsion Track Size : 2" Flag & Jambs Separate Track Type : Standard Mount Type : Bracket Track Radius : 15 Handles : Standard Handles Included Hinges : Show No Hinge Step Plates : Show No Step Plate Lock : Inside Slide Lock Lock Options : No Lock Hole (Std with no lock and inside slide lock optional on #1 & #3) Other Items : Gold Bar Upgrade Shaft : Standard Shaft Struts : 1 Extra Strut Vinyl Stop Mold : Bronze	

Total Due \$6,989.00

Thank You for Choosing AAA Garage Door!

This quote is for installation in prepared openings with proper clearances unless otherwise stated. AAA Garage Door shall not be responsible for any electrical work required for the above job.

