



Grady Hastings <grady@mcneilcompany.com>

Front Door Quote - Crockett

Grand Entry Doors ® Kevin <kevin@grandentrydoors.com>

Tue, Aug 11, 2026 at 5:22 PM

To: Grady Hastings <grady@mcneilcompany.com>

Good evening. This would have to be made custom. Due to the size we would require this to be 2-1/4" vs the standard 1-3/4". We would also require multipoint locking. The cost for the unit including delivery and multipoint locking and handles would be \$13,800 and would ship in 15-16 weeks.

The price quoted is for the unfinished (not stained) pre-hung unit which includes the jambs, brickmould, weather-stripping, door sweep, adjustable threshold (sill), 4x4 ball bearing hinges. **Does not include interior casing. If you wish to purchase interior casing please contact us.**

****Local building regulations, codes, and laws can vary greatly from one area to another. It is crucial that you consult with your professional contractor and adhere to the specific regulations and codes relevant to your location. Therefore, it is your responsibility as the customer to review and understand the applicable laws, codes, and regulations in your jurisdiction to ensure that the construction, installation, and use of our doors comply with local requirements.

****Requirements for adequate overhang protection: Installer must ensure proper protection requirements are provided where the door will be installed. All doors must be installed providing sufficient protection from exposure to weather including excessive moisture/rain as well as excessive heat due to sun exposure. This protection required includes adequate overhang distance that is at a minimum projection from the home at one half the distance from the floor of the overhang to the ceiling of the overhang. Additionally, the overhang should extend a minimum of 3 ft in width from each side of the door unit. Failure to provide adequate overhang protection will void the warranty.

All wood doors are constructed using floating panels. This construction method allows for expansion and contraction. Exposure to severe moisture such as rain in an unprotected environment may result in water penetration through the panels and is not considered a defect. In the event of water penetrating through the edges of the panels in this environment, it will be the consumers responsibility to caulk and or provide a remedy for the water penetration.

****Staining or painting the door black or any other dark opaque colors will void the warranty. These colors cause harm to the wood components by absorbing excess heat/UV rays.

Feel free to email me at kevin@grandentrydoors.com or call me direct at 704-912-1984 if you have any questions. Thank you for your consideration.

- Kevin




Grand Entry Doors ®

704-912-1280 | 704-912-1984 | grandentrydoors.com

kevin@grandentrydoors.com

2216 Hawkins Street, Charlotte, NC 28203



Visit Our Showroom

[Quoted text hidden]

[Quoted text hidden]

<FrontDoor2026.08.11_Crockett.pdf>

The content of this email is intended for the person or entity to which it is addressed only. This email may contain proprietary, business-confidential and/or privileged material. If you are not the intended recipient of this message, be aware that any use, review, retransmission, distribution, reproduction or any action taken in reliance upon this message is strictly prohibited. If you received this in error, please contact the sender and delete the material from all computers.